

---

**To: Outback eDriveX Users**  
**From: Global Customer Care**

**Subject: eDriveX Software v2.2.2.1.28269 Update**

---

**Products Affected:** eDriveX


**Scope:** This document provides software update installation instructions for the Outback eDriveX

---


**Note:** Ensure the ECU is updated *before* updating the terminal

### Installation Instructions


- 1) Open a web browser and go to [outbackguidance.zendesk.com](http://outbackguidance.zendesk.com)
- 2) Navigate to **Software > \*your terminal\*** and click on **2.2.2.1.28269** to download the software
- 3) Click on the downloaded **UsbUpdate\_2\_2\_2\_1\_28629.zip** when complete and the file will open
- 4) Select **Extract all** at the top of the screen



- 5) Note the folder to which the files will be extracted and click **Extract**



- 6) Copy the **release** folder onto the root of an empty USB drive (ensure the folder is named release)
- 7) Power on the eDriveX ECU and insert the USB drive into one of the USB ports on the ECU
- 8) Touch the **Wrench icon > System**. When the USB drive is recognized to have an update available, the **Update ECU** button will turn blue



- 9) Touch the **Update ECU** button and wait for the update, which can take up to fifteen minutes, to complete. Do not stop or interrupt the update process until the terminal supplies instructions to remove the USB drive and reboot the eDriveX.
- 10) After rebooting, verify a successful update by checking the **Steering tab > Firmware** version has been changed to **2.2.2.1.28269**